

Recall Date: February 15, 2017 Recall Number: 17-DRAFT 2/6/17 4 p.m. ET

# **Britax Recalls Strollers Due to Fall Hazard**

## **Recall Summary**

Name of Product: Britax B-Agile and BOB Motion Strollers with Click & Go receivers

**Hazard:** A damaged receiver mount on the stroller can cause the car seat to disengage and fall unexpectedly, posing a fall hazard to infants in the car seat.

#### Remedy: Repair

Consumers should immediately stop using their Click & Go receiver mounts and contact Britax for a free repair kit for single strollers. Owners of the recalled double strollers should stop using them with car seats attached.

Consumers can continue to use their stroller or car seat independently without the car seat attached to the stroller.

**Consumer Contact:** Britax online at <u>www.us.britax.com</u> and click on the Safety Notice on the homepage or visit us.britax.com/recall, call toll-free at 844-227-0300 from 8:30 a.m.to 7 p.m. ET Monday through Friday and from 9 a.m. to 3 p.m. ET Saturday or email Britax at stroller.recall@britax.com.

## **Recall Details**

**Units:** About 676,000 (in addition, about 36,000 were sold in Canada and about 4,600 were sold in Mexico)

**Description:** This recall involves Britax B-Agile and BOB Motion strollers (when used as a travel system with a car seat carrier attached). All models are folding, single or double occupant strollers and have Click & Go receiver mounts that attach the car seat carrier to the stroller frame. All colors of the stroller are included. The model number can be found on the inside of the stroller's metal frame near the right rear wheel for single strollers and in the front middle underside of the frame on double strollers. Recalled model numbers include:

### **B-Agile:**

S01298600, S01298700, S01635200, S02063600, S02063700, S02063800, S02063900, S02064000, S03803400, S03803500, S03803700, S03803800, S03803900, S04144400, S04144500, S04144600, S04144700, S04144800, S04144900, S04145000, S04183700,

S04183800, S04184000, S04281200, S04281300, S04402800, S04437700, S04628500, S04884200, S04884300, S04884400, S04884500, S04975600, S04978900, S05060600, S05260200, S05511600, S05511700, S865800, S865900, S874300, S874400, S874500, S877200, S890100, S896000, S896200, S896600, S907200, S907300, S907400, S907500, S907600, S910200, S910300, S910400, S910500, S912300, S914300, S914500, S914700, S914900, S915200, S915400, S917400, S921800, S921900, S923700, U341763, U341764, U341782, U341783, U341825, U341826, U341828, U341X82, U34X782, U361763, U361818, U361819, U361825, U391875, U451835, U451837, U451841, U461763, U461764, U461782, U461783, U461825, U461826, U461828, U471818, U471819, U491842, U491843, U491844, U491908, U491909, U491910, U511875, U511877, U551835, U551837, U551841, U551861, U551862, U551863, U551864, U551865, U551905, U551906, U691878, U691879, U691881, U691882, U691884, U691904, U691905, U721895, U721896

#### **BOB Motion:**

S888600, S890200, S890300, S890400, S890500, S909700, S910600, S910700, S910800, S910900, S912600, U391820, U391821, U391822, U481820, U481821, U481822, U501820, U501821, U501822, U501907

**Incidents/Injuries:** Britax has received 33 reports of car seats unexpectedly disconnecting from the strollers and falling to the ground, resulting in 26 reports of injuries to children, including scratches, bruises, cuts and bumps to the head. In addition, Britax is aware of 1,343 reports of strollers with damaged Click & Go receiver mounts.

**Sold at:** Babies R Us, buy buy Baby, Target and other stores nationwide, and online at Amazon.com, albeebaby.com, buybuybaby.com, diapers.com, ToysRUs.com and other websites from May 2011 through February 2017 for between \$250 and \$470 for the stroller travel systems.

Importer: Britax Child Safety Inc., of Fort Mill, S.C.

Manufactured in: China

**Note:** Health Canada's press release is available at: http??

Profeco's press release is available at <u>http://www.gob.mx/profeco/documentos/alertas-al-</u> consumidor-2017?state=published

## **Photos**



Britax-B-Agile stroller (in travel system mode)



Britax B-Agile double stroller (in travel system mode)



B-Agile 4 stroller (in travel system mode)



**BOB-Motion stroller (in travel system mode)** 

#### About U.S. CPSC:

The U.S. Consumer Product Safety Commission is charged with protecting the public from unreasonable risks of injury or death associated with the use of thousands of types of consumer products under the agency's jurisdiction. Deaths, injuries, and property damage from consumer product incidents cost the nation more than \$1 trillion annually. CPSC is committed to protecting consumers and families from products that pose a fire, electrical, chemical or mechanical hazard. CPSC's work to ensure the safety of consumer products - such as toys, cribs, power tools, cigarette lighters and household chemicals – contributed to a decline in the rate of deaths and injuries associated with consumer products over the past 40 years.

Federal law bars any person from selling products subject to a publicly-announced voluntary recall by a manufacturer or a mandatory recall ordered by the Commission.

To report a dangerous product or a product-related injury go online to <u>www.SaferProducts.gov</u> or call CPSC's Hotline at 800-638-2772 or teletypewriter at 301-595-7054 for the hearing impaired. Consumers can obtain news release and recall information at <u>www.cpsc.gov</u>, on Twitter <u>@USCPSC</u> or by subscribing to CPSC's <u>free e-mail</u> newsletters.

#### **CPSC Consumer Information Hotline**

Contact us at this toll-free number if you have questions about a recall: 800-638-2772 (TTY 301-595-7054) Times: 8 a.m. – 5:30 p.m. ET; Messages can be left anytime Call to get product safety and other agency information and to report unsafe products.

#### Media Contact

Please use the phone numbers below for all media requests. Phone: 301-504-7908 Spanish: 301-504-7800